

序号	报告编号	发布日期	结论	影像资料
40	GX-B1342/21-9-25002	2025. 4. 21	1. 矿井总进风量： 3919.8 m3/min; 2. 矿井总回风量： 4183.7 m3/min; 3. 全系统计算阻力 值：1398.76 Pa; 4. 全系统测定阻力 值：1383.8 Pa; 5. 矿井等积孔：2.50 m2。	 2025.03.26
41	GX-B1340/23-9-25014	2025. 4. 27	1#在用主要通风机系统 合格。	 2025.04.01

42	GX-B1340/23-9-25015	2025. 4. 27	在用主要通风机系统合格	
43	GX-B1342/21-9-25003	2025. 4. 27	1. 矿井总进风量： 1505.3 m3/min; 2. 矿井总回风量： 1557.6 m3/min; 3. 全系统计算阻力 值：366.47 Pa; 4. 全系统测定阻力 值：359.7 Pa; 5. 矿井等积孔： 1.68m2。	

44	GX-B1343/21-9-25017	2025. 4. 29	1. 矿井总进风量: 105.83 m³/s, 总回风量: 107.95 m³/s; 2. 主通风机风量: 110.52 m³/s; 3. 矿井有效风量: 87.69 m³/s; 4. 矿井有效风量率: 79.3 %; 5. 通风机负压 (机站风压): 2530 Pa; 6. 矿井通风阻力: 2501.3 Pa。	 2025.04.03
45	GX-B1343/21-9-25022	2025. 4. 29	1. 矿井总进风量: 220.40 m³/s, 总回风量: 222.82 m³/s; 2. 主通风机风量: 225.79 m³/s; 3. 矿井有效风量: 155.72 m³/s; 4. 矿井有效风量率: 69.0 %; 5. 通风机负压 (机站风压): 中央回风井主通风机 2860Pa, 南回风井主通风机 598Pa; 6. 矿井通风阻力: 中央回风井通风系统2734.9Pa, 南回风井通风系统590.9Pa。	 2025.04.09

46	GX-B1340/23-9-25018	2025年4月30日	1#在用主要通风机系统合格。	
47	GX-B1340/23-9-25019	2025年4月30日	2#在用主要通风机系统合格。	

48	GX-B1370/21-9-25008	2025年4月30日	存在问题： 未进行多网、多系统融合，系统之间无法进行多系统联动。 建议：加强甲烷超限断电闭锁和故障闭锁功能维护。 除上述问题外，其余所检项目合格。	
49	GX-B1594/21-2500010TH1	2025年4月30日	除风量、风压不判定外，其余所检项目合格。	

50	GX-B1594/21-2500012TH1	2025年4月30日	除风量、风压不判定外，其余所检项目合格。	 A photograph showing two miners in a dark tunnel. They are wearing blue and red work clothes and white hard hats with headlamps. They are standing on a rocky floor next to some equipment.
51	GX-B1594/21-2500013TH1	2025年4月30日	除风量、风压不判定外，其余所检项目合格。	 A photograph showing two miners in a dark tunnel. They are wearing blue and red work clothes and white hard hats with headlamps. They are standing on a rocky floor next to some equipment.

52	GX-B1594/21-2500014TH1	2025年4月30日	除风量、风压不判定外，其余所检项目合格。	
53	GX-B1594/21-2500015TH1	2025年4月30日	除风量、风压不判定外，其余所检项目合格。	

54	GX-B1371/21-9-25011	2025年4月30日	存在问题： 一氧化碳传感器调校记录表中传感器型号及标准气样填写错误。 建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。	
55	GX-B1371/21-9-25012	2025年4月30日	存在问题： 1、无监测监控操作规程、值班制度； 2、无设备台账、传感器调校记录表、报警记录月报表。 建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。	

56	GX-B1371/21-9-25013	2025年4月30日	存在问题： 传感器调校记录表中无标准气样值、传感器显示值、声光报警是否正常栏。 建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。	
57	GX-B1376/25-2500003TH1	2025. 4. 30	存在问题：地面中心站无法向指定区域或分站识别范围内的识别卡发出呼叫信息。 建议：加强对系统的日常管理与维护。 综合判定：合格。	

58	GX-B1376/25-2500004TH1	2025. 4. 30	存在问题： 1、巡检周期时间超过标准要求20s； 2、无设备、仪表台帐、中心站运行日志、监测日（班）报表、设备使用情况月报表。 建议：加强对系统的日常管理与维护。 综合判定：合格。	
----	------------------------	-------------	---	---