

序号	报告编号	发布日期	结论	影像资料
15	GX-B1378/22-B-25189~B-25192	2025. 7. 14	所检项目合格	
16	GX-B1378/22-B-25193	2025. 7. 14	所检项目合格	

17	GX-B1377/22-B-25201	2025. 7. 15	所检项目合格	 A photograph showing two men in light blue short-sleeved shirts standing behind a large, light-colored industrial machine. They appear to be inspecting or operating the machine. The background shows a room with yellow curtains and a red fire alarm pull station on the wall. A timestamp '2025.7.10' is visible in the bottom right corner of the photo.
18	GX-B1377/22-B-25202	2025. 7. 15	所检项目合格	 A photograph showing two men in light blue short-sleeved shirts standing behind a large, light-colored industrial machine, similar to the one in the first photo. They are looking at the machine. The background is the same room with yellow curtains and a red fire alarm pull station. A timestamp '2025.7.10' is visible in the bottom right corner of the photo.

19	GX-B1378/22-B-25186~B-25188	2025. 7. 15	所检项目合格	
20	GX-B1377/22-B-25205	2025. 7. 16	所检项目合格	